

Photographs of select violations of wetland and waterway permit conditions along the Enbridge Construction Corridor. Wisconsin Wetlands Association (WWA) compiled the photos from daily reports submitted to WDNR by Independent Environmental Monitors assigned to monitor the environmental performance of Enbridge's construction crews.

For more information contact WWA's Policy Specialist, Erin O'Brien at 608-250-9971 or erin.obrien@wisconsinwetlands.org



**MP 317.3. Silt fence does not extend across entire disturbed ROW
Report 4-DD-102 - 2/7/08**



**Sediment-laden water flowing into Wetland CO-W17
Report 4-DD-097 - 1/26/08**



**Wetland and upland spoil not separated at DA-W5 boundary
Report 4-DD-094 – 1/16/08**



**Location where track hoe walked off the mats in Wetland
Report 4-DD-076 – 11/10/07**



**Wetland WO-W48 subsoil on topsoil
Report 3-JV-019 – 10/13/07**



**Eau Claire River, DO-S22, Overland Pump Around Scouring
Report 1b-ST-015 – 10/11/07**



**North end wetland RU-W83. Sediment entering wetland where silt fence is in need of repair.
Report 2-JV-116 – 10/6/07**



**Spoil outside eastern edge of ROW in Wetland
Report 4-DD-048 – 9/8/07**



**Sediment, ECD Blowout in wetland
Report 1C-ST-020 – 8/30/07**



**Trib to Hauer, SA-S3, Downstream Sediment Deposit,
Sediment Extends 100 yds to the West of ROW
Report 1C-ST-019 – 8/28/07**



**Sediment deposited in Wetland CO-W23
Report 4-DD-027 – 8/7/07**



Sub-soil on topsoil, wetland. Report 2-JV-072 – 7/24/07